

NSBS Physical Progress Summary as at 30-11-2019 in Eastern Province

PROJECT	Activity	Started Activities	0-25 % Tasks Completed	26-50 % Tasks Completed	51-75 % Tasks Completed	76-100 % Tasks Completed	No of Task Completed
A	Class room & Other Buildings (5 Mn)	32	23	8	1		
	Teachers Quarters (6 Mn)	0					
	Principals' Quarters (5 Mn)	0					
	Cafeteria (5 Mn)	0					
	Sports Complex - Phase 1 (16 Mn)	0					
	Junior Secondary Laboratory (15 Mn)	14		2	2	1	9
	Aesthetic Units - Type 1 (30 Mn)	1					1
	Aesthetic Units - Type 2 (14 Mn)	0					
	Developmen of School Plant for safe environment (2 Mn) (minor repairs)	61					61
	Major Repairs (9.5 Mn)	40	6	14	8	7	5
B	Primary Learning Resource Centre - Single Storied (10 Mn)	52		3		1	48
	Junior Secondary Laboratory (15 Mn)2	16	1		2		13
	Technical Building (15 Mn)	30	4	2	1	4	19
	Developmen of School Plant for safe environment (2 Mn)	99					99
C	Class room & Other Buildings (4 Mn)	16	8	8			
	Development of School Plant for safe environment (5 Mn)	68	15	22	13	14	4
D	Primary Learning Resource Centre - Single Storied Buildings	18	3	4	3	1	7
	Primary Learning Resource Centre - Double Storied Buildings	46	2	3	2	2	37
	Primary School Development (Minor epairs)	443	5	1			437
E	Providing Teacher Quarters	41				4	37
F	Providing Sanitary Facilities	366	12	2	5	6	341
	Providing Water Facilities	230	2				228
G	Providing Electricity	595	3	1	14		577
H	Upgrading Estate Schools to Secondary Level - New Construction	0					
	Upgrading Estate Schools to Secondary Level - Repairs	0					
J	New Construction- Dental Health Facilities	0					
	Renovation - Dental Health Facilities	11	1				10
	Total	2179	85	70	51	40	1933