


**NSBS Physical Progress Summary as at 30-11-2019 in Western Province**

PROJECT	Activity	Started Activities	0-25 % Tasks Completed	26-50 % Tasks Completed	51-75 % Tasks Completed	76-100 % Tasks Completed	No of Task Completed
A	Class room & Other Buildings (5 Mn)	4			2		2
	Teachers Quarters (6 Mn)	20		1	3	4	12
	Principals' Quarters (5 Mn)	36	2	2	1	5	26
	Cafeteria (5 Mn)	10		2			8
	Sports Complex - Phase 1 (16 Mn)	0					
	Junior Secondary Laboratory (15 Mn)	10		4		3	3
	Aesthetic Units - Type 1 (30 Mn)	0					
	Aesthetic Units - Type 2 (14 Mn)	0					
	Developmen of School Plant for safe environment (2 Mn) (minor repairs)	74			2		72
	Major Repairs (9.5 Mn)	72	1		1		70
B	Primary Learning Resource Centre - Single Storied (10 Mn)	42	5		4	4	29
	Junior Secondary Laboratory (15 Mn)2	10	2	1	1	3	3
	Technical Building (15 Mn)	27	1	3	2	3	18
	Developmen of School Plant for safe environment (2 Mn)	196	11	2	2	1	180
C	Class room & Other Buildings (4 Mn)	4		2	1		1
	Development of School Plant for safe environment (5 Mn)	86	1				85
D	Primary Learning Resource Centre - Single Storied Buildings	9					9
	Primary Learning Resource Centre - Double Storied Buildings	3			2	1	
	Primary School Development (Minor epairs)	351	1	2	1		347
E	Providing Teacher Quarters	0					
F	Providing Sanitary Facilities	224	8			7	209
	Providing Water Facilities	10	3				7
G	Providing Electricity	190	15			1	174
H	Upgrading Estate Schools to Secondary Level - New Construction	0					
	Upgrading Estate Schools to Secondary Level - Repairs	0					
J	New Construction- Dental Health Facilities	0					
	Renovation - Dental Health Facilities	2					2
	<b>Total</b>	<b>1380</b>	<b>50</b>	<b>19</b>	<b>22</b>	<b>32</b>	<b>1257</b>

Completed  
Ongoing



91%  
10%