

NSBS Physical Progress Summary as at 31-05-2020 in North Western Province

PROJECT	Activity	Started Activities	0-25 % Tasks Completed	26-50 % Tasks Completed	51-75 % Tasks Completed	76-99 % Tasks Completed	No of Task Completed
A	Class room & Other Buildings (5 Mn)	49	4	4		7	34
	Teachers Quarters (6 Mn)	0					
	Principals' Quarters (5 Mn)	0					
	Cafeteria (5 Mn)	0					
	Sports Complex - Phase 1 (16 Mn)	0					
	Junior Secondary Laboratory (15 Mn)	15	1			1	13
	Aesthetic Units - Type 1 (30 Mn)	4	1				3
	Aesthetic Units - Type 2 (14 Mn)	3					3
	Developmen of School Plant for safe environment (2 Mn) (minor repairs)	53		1	4		48
	Major Repairs (9.5 Mn)	0					
B	Primary Learning Resource Centre - Single Storied (10 Mn)	77	1	3	2		71
	Junior Secondary Laboratory (15 Mn)2	26		3	1	1	21
	Technical Building (15 Mn)	47	1	3	3	1	39
	Developmen of School Plant for safe environment (2 Mn)	95		2	2		91
C	Class room & Other Buildings (4 Mn)	1					1
	Development of School Plant for safe environment (5 Mn)	0					
D	Primary Learning Resource Centre - Single Storied Buildings	55		1	2		52
	Primary Learning Resource Centre - Double Storied Buildings	29					29
	Primary School Development (Minor epairs)	49					49
E	Providing Teacher Quarters	0					
F	Providing Sanitary Facilities	121	1	5	3	1	111
	Providing Water Facilities	11					11
G	Providing Electricity	697	1				696
H	Upgrading Estate Schools to Secondary Level - New Construction	0					
	Upgrading Estate Schools to Secondary Level - Repairs	0					
J	New Construction- Dental Health Facilities	4					4
	Renovation - Dental Health Facilities	20					20
	Total	1356	10	22	17	11	1296

Class room & Other Buildings (B) - North Western Province	13					13
Major Repairs (B) - North Western Province	1					1
Class room & Other Buildings (D) - North Western Province	30		3	1	3	23